



Axis Response Group, LLC

PO BOX 2848 GLENVIEW, ILLINOIS 60025

Tel: 847-998-6811 Fax 847-998-6813

Environmental & Demolition Services

July 19, 2011

CLP, INC
8119 WHITE
LYONS, ILLINOIS 60534

Re: Asbestos Survey/Sampling/Analysis- at 7209 HARVARD IN FOREST PARK, IL

AXIS RESPONSE GROUP, LLC conducted an asbestos inspection, to comply with Cook County Department of Environmental Control in support of the demolition project scheduled for the above referenced site. An Illinois Department of Public Health Licensed inspector IDPH# 100-9971 conducted the survey and suspect materials taken were Positive at location of sampling. See Chain of Custody below.

METHODOLOGY

Bulk samples were taken to EMSL Analytical, Inc. and analyzed by Polarized Light Microscopy (PLM) with dispersion staining Method EPA 600/R-93/116 by a laboratory which is accredited by the American Industrial Hygiene Association (AIHA) and which successfully participates in the National Institute of Science and Technologies National Voluntary Laboratory Accreditation Program (NIST-NVLAP). Suspect ACM was not unnecessarily disturbed for sampling, A NIOSH approved respirator was worn during bulk sampling of friable materials, A core was removed by gently cutting and penetrating all layers of the material, including paint and protective coating, Each sample was placed in a plastic laboratory bag and labeled with a discrete sample ID.

Asbestos Containing Materials

Bulk samples of suspect ACMS were collected. Samples were then analyzed for asbestos content. EPA and OSHA regulations define ACM as any material containing greater than 1% asbestos. The following is a summary of the results of the materials sampled and quantity estimates of the material, in the various locations.

*****Inspection Limitations*****

Our inspection investigation was performed using the degree of care and skill ordinarily exercised under similar circumstances by reputable environmental consultants practicing in this or other localities. The information in this report is deemed reliable but there cannot be a guarantee that all hazardous or potentially hazardous conditions have been located or identified. Some of the reasons for this are:

*When sampling was conducted, it was performed on a random basis and the material sampled was assumed to be homogenous. The possibility does exist that material composition may differ from the sampling location.

*The inspection conducted was not an (AHERA) inventory. Therefore, All ACM may not have been identified.

*Unless specifically noted, our findings and areas we selected to be sampled are based on visual observations. Materials and conditions, which are concealed or are inaccessible, may not have been discovered.

SUMMARY OF RESULTS		AXIS RESPONSE GROUP, LLC		Chain of Custody
Client:	7209 HARVARD IN FOREST PARK, IL	DATE	JULY 19, 2011	
Sample	Material Description	Type	Location /Quantity	YES or ND
1,2,3	FLOOR TILES BROWN	Chrysotile	BASEMENT AREAS	YES
4,5,6	MASTIC ON FLOOR TILES BROWNE	Non-fibrous	BASEMENT AREAS	ND
7,8,9	WALLBOARD COMPOSITES	Non-fibrous	BASEMENT AREAS	ND
10	RED FLOORING STAIRWAY	Chrysotile	STAIRWAY	YES
11	MASTIC ON RED FLOORING STAIRWAY	Chrysotile	STAIRWAY	YES
12,13,14	BLUE LINOLUEM FLOORING	Chrysotile	1 ST FLOOR AREAS	YES
15,16,17	BROWN FLOORING	Non-fibrous	1 ST FLOOR AREAS	ND
18	12X12 FLOORING	Non-fibrous	1 ST FLOOR AREAS	ND
19,20,21	ROOFING FIELD	Non-fibrous	EXTERIOR ROOFING	ND

* Please Note -Suspect material might be encountered during demo activities behind walls, over ceiling, in crawl spaces or inaccessible areas, in such event Suspect material is found demo contractor will need to stop work and notify the Cook County Department of Environmental Control and hire a Licensed Abatement Contractor.

If you have any questions or concerns please contact us at 847-998-6811.

Sincerely
Axis Response Group
Jose Rodriguez
Project Manager

Tel: 847-998-6811 Fax 847-998-6813

www.axisresponsegroup.com